



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA20008446/T1vf3e2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Date : 02-09-2020



Code : AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLH 2739E
Policy No.	BVPISB0047511903	Coverage (\$)	0.00
Claim No.	NSV2000226/HLF	Excess (\$)	0.00
Assign From	MOTORSURVEY	Assign Date	14/08/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJ5KC5GG079453	Colour	BRONZE
Odometer	76639	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/08/2020	Inspection Date	17/08/2020
Survey held at	36 TOH GUANRD EAST #01-36		
Repairer	WAH HONG & CREDIT PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$66,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------