55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 44711

Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0560/2020/NS

**Date** : 12-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Li Yuanfang

Address : Blk 339 Kang Ching Road

#08-326

Singapore 612339 : HP +65 96289276

Telephone : HP +65 96289276

Type of Claim : Own Damage Claims

Policy No. : 1800143196-01

Vehicle No : SMF 9486 L

Model Code : Audi A3 SPORTSBACK 1.0 TF

Model / Year : Nov-18
Engine No : CHZ B22242

Chassis No : WAUZZZ8V6KA008776

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 5-Aug-20

Place of Accident : Sims Edge 1 Geylang East Ave 2

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

#### Estimated Labour Charges for Accident Vehicle SMF 9486 L

S/N	Nature of Jobs			timated harges	Survevor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$	280.00	
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$	480.00	~
3	To dismantle and renew rear bumper. To cut out and reweld rear end panelling outer and inner. Reorganise crash management components. Reinstall all parts removed.	E	\$	3,500.00	500 /
4	To respray rear bumper, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.		\$	3,000.00	550. /
5	To renew lhs rear exhaust silencer. To align to psition.	S/N	\$	480.00	8
6	To carry out diagnostic check.	S/N	\$	192.00	<b>/ /</b>
	TOTAL LABOUR CHARGES	:	\$ 7	,932.00	-

55 Ubi Road 1, Singapore 408699 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 9486 L

S/N	Parts Description		Damage Part S/NETT	s & Prices Remarks
1	REAR BUMPER Distorted	\$	1,847.00 🛩	1477.60
2	REAR BUMPER FIXING PARTS	\$	191.00 -	
3	REAR BUMPER LOCKING MECHANISM - LH / RH 2 2	\$	28.00 >	
4	WHEEL HOUSING LINER ADAPTER - LH / RH	\$	37.00 X	
5	REAR BUMPER SPOILER	\$	234.00 ¬	× NN
6	REAR LIGHT REFLECTOR - LH ?	\$	30.00 7	
7	LED TAIL LIGHT - LH abl m	\$	867.00 €	
8	REAR BUMPER SIDE REINFORCEMENT BEAM BEAM	\$	565.00 —	451.60
9	REAR BUMPER BRACKET - LH	\$	27.00 +	
10	REAR BUMPER BRACKET - RH	\$	28.00 £	
11	REAR BUMPER GUIDE SECTION - LH Cra	\$	66.00 ×	52.40 🗸
12	REAR PARKING AID SENSOR - INNER / OUTER ? 2		TBC ?	X NN
13	CROSS PANEL REINFORCEMENT	\$	725.00 7.	X NN
14	REAR CROSS PANEL	\$	242.00 ?	X NN
15	REAR SILENCER Z	\$	615.00 ×	
16	REAR SILENCER DUAL CLIP Le a	\$	57.00 ₹	
17	EXHAUST SYSTEM RETAINER 2	\$	79.00 ×	
18	AUDI EMBLEM	\$	122.00+	
19	A3 INSCRIPTION THE M	\$	95.00	
20	PACKING ADHESIVE	\$	18.00	
21	STONE CHIP S/N	\$	180.00?	XNN
22	CAVITY WAX 7. S/N	\$	140.00?	XNN
23	ACRYLIC SEALANT ? S/N	\$	180.00 7	XNN
24	SUNDRIES ? nec	\$	300.00 ?	69.28 🗸
	TOTAL SPARE PARTS CHARGES : TOTAL LABOUR CHARGES : GRAND TOTAL :	\$ \$ \$	6,673.00 7,932.00 14,605.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

**Telefax** 

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

At Anthorsed, 03 Days.

**Please Note** 

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant