LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From To: From To

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Cecilia Low Date: 20 Aug 2020

Preliminary Advice

Insured Vehicle No : GBH8871J

 TP Vehicle No
 : GBE9804M
 Accident Date
 : 13/08/2020

 Make
 : NISSAN NV200
 Assignment Date
 : 14/08/2020

Date of Inspection : 19/08/2020 Est. Duration of Repair : 7

Inspection At : AUTOLUTION INDUSTRIAL PTE LTD (HQ)

19 UBI ROAD 4 SINGAPORE 408623

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,247.08
Revised Amount	:S\$	4,972.48
Check Items (Estimated)	:S\$	1,021.76
Total	:S\$	5,994.24

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: survey on wp