

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Shawn Ngo Sau Wei

Date: 03 Sep 2020

Preliminary Advice

Insured Vehicle No	: SLG2449Y		
TP Vehicle No	: SMS4373T	Accident Date	: 13/08/2020
Make	: MERCEDES-BENZ C200	Assignment Date	: 14/08/2020
Date of Inspection	: 17/08/2020	Est. Duration of Repair	: 5 days
Inspection At	: Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339 Singapore 470130		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,244.00
Revised Amount	:S\$	8,660.61
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,660.61
Lump Sum Repair	:S\$	6,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.