

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 25 Aug 2020

Preliminary Advice

Vehicle No	: SDS5525Y	Accident Date	: 14/08/2020
Make	: AUDI Q2	Policy No.	: 1800115567
Assignment Date	: 17/08/2020	Excess	: S\$400.00
Date of Inspection	: 17/08/2020	Est. Duration of Repair	: 6
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,959.00 (inclusive supp)
Revised Amount	:S\$	9,298.00 (inclusive supp)
Check Items (Estimated)	:S\$	11,971.00
Total	:S\$	21,269.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	43,375.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,625.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 1,117.00.