

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45481

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0573/2020/NS
Date	:	15-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Ang Yoke Pheng
Address	:	5C Chancery Hill Road Singapore 309647
Telephone	:	Office +65 98399366
Type of Claim	:	Own Damage Claims
Policy No.	:	1800115567
Vehicle No	:	SDS 5525 Y
Model Code	:	Audi Q2 1.0 TFSI S TRONIC
Model / Year	:	Sep-18
Engine No	:	CHZ A90358
Chassis No	:	WAUZZZGA5KA000621
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Aug-20
Place of Accident	:	Dunearn Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6365 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDS 5525 Y

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00 ✓	
2	To remove and transfer both headlight control units and power modules.	S/N \$ 800.00 ✓	
3	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ✓	24/08/20
4	To dismantle and renew front bumper and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,000.00 500 + 1250 = 1750	
5	To respray front bumper.	\$ 1,200.00 550	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 5525 Y

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
1	FRONT BUMPER <i>de /</i>	\$	1,854.00	
2	FRONT BUMPER FIXING PARTS ?	\$	343.00	
3	FRONT BUMPER GRILLE - CENTRE ?	\$	195.00	
4	FRONT BUMPER AIR GUIDE GRILLE - <i>su /</i> LH / RH 1 <i>X</i>	\$	334.00	
5	FRONT BUMPER END CAP - LH / RH <i>X</i>	2 \$	68.00	
6	FRONT BUMPER SPOILER <i>de /</i>	\$	296.00	
7	FRONT BUMPER CLOSING ELEMENT ?	\$	154.00	
8	FRONT WHEEL SPOILER - LH / RH <i>X</i>	2 \$	68.00	
9	RADIATOR GRILLE <i>ca /</i>	\$	1,395.00	
10	RADIATOR GRILLE STRIKER PLATE ?	\$	123.00	
11	FRONT BUMPER CARRIER ?	\$	679.00	
12	FRONT BUMPER FOAM FILLER PIECE <i>truled</i>	\$	77.00	✓
13	FOAM FILLER PIECE COVER ?	\$	99.00	
14	FRONT BUMPER GUIDE SECTION - LH / RH ?	2 \$	70.00	
15	AIRCON STICKER <i>X</i>	NEC \$	8.00	
16	CAUTION SIGN STICKER <i>X</i>	NEC \$	14.00	
17	WHEEL HOUSING LINER - LH / RH <i>X</i>	2 \$	388.00	
18	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>	\$	57.00	
19	HEADLIGHT MOUNTING - LH / RH ?	2 \$	234.00	
20	LED HEADLIGHT - LH / RH ?	2 \$	9,718.00	
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 16,174.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 5525 Y

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	LIFT CYLINDER - LH / RH X	2	\$ 282.00	
22	LIFT CYLINDER HOSE X		\$ 175.00	
23	LOCK CARRIER X		\$ 983.00	
24	AIRCON CONDENSER <i>Revised</i>		\$ 545.00	✓
25	EXTERNAL TEMPERATURE SENSOR ?		\$ 56.00	
26	READY MIX COOLANT <i>See</i>		\$ 177.00	✓
27	RADIATOR AIR GUIDE - (LH) RH <i>Int. could</i>	2	\$ 60.00 30	
28	RADIATOR AIR GUIDE - UPPER CENTRE <i>could</i>		\$ 22.00	✓
29	FRONT WHEEL COVER - LH / RH <i>see</i>	2	\$ 636.00	
30	FRONT NO PLATE <i>St</i>	S/N	\$ 60.00	
31	SUNDRIES ?		\$ 300.00	
TOTAL SPARE PARTS CHARGES		:	\$ 19,470.00	
TOTAL LABOUR CHARGES		:	\$ 7,872.00	
GRAND TOTAL		:	\$ 27,342.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Adrian

24/08/20

add 3 repair days