

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI20008533/Gtf3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date: 01-10-2020 Code: GAI	
1. Policy Particulars :- THIF				
	Insured Veh.	SMS 5155A	Veh. Inspected	SMS 2820H
-	Policy No.	- GIVIO 0 100/1	Coverage (\$)	0.00
	Claim No.	CLMOMVP000001085	Excess (\$)	0.00
	Assign From	KELYVN NGIAN	Assign Date	14/08/2020
2.	Assignition		culars & Condition	1 1/00/2020
	Make & Model	HYUNDAI AE IONIQ	c.c	1580
-	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHC851CVLU201011	Colour	BLACK
	Odometer	49338	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
\vdash	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	07/08/2020	Inspection Date	17/08/2020
	Survey held at	SPARK CAR-205 BRADDELL RE)	
	Repairer	-		
5a.	a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			