



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18019305/Gqf3s2-1		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 09-09-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 3282C	Veh. Inspected	SKE 9627B	
Policy No.	DMCVSN1686801701	Coverage (\$)	0.00	
Claim No.	SNM18D05003C02	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	15/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S60 T4	c.c	1596	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	YV1FS485BC2126453	Colour	BLACK	
Odometer	134385	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	235/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	235/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	235/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2018	Inspection Date	24/10/2018	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		