

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GOH GIAM HWEE
31 FERVALE ROAD
#12-57
SINGAPORE 797417

Estimate No: MC1901340
Date: 14 Aug 2020
Policy No: PNPV2019-00013778
Veh Reg No: SMK5492T
Make/Model: TOYOTA LEXUS IS250C
A STD

ATTN:

Your Ref No: SMK5492T
Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBE2471K

Estimate Repair Cost to Vehicle No :SMK5492T

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP LH	1 PC	1,328.50	
2 HEADLAMP LOWER BEAM LH	1 PC	170.10	
3 FRONT BUMPER	1 PC	571.50	
4 FRONT BUMPER SIDE RETAINER LH	1 PC	74.60	
5 FRONT BUMPER CLIPS	12 PC	54.00	
6 FRONT BUMPER LOWER GRILLE	1 PC	175.70	
7 FRONT BUMPER TOW COVER	1 PC	20.60	
8 FRONT BUMPER SPONGE	1 PC	128.00	
9 FRONT BUMPER REINFORCEMENT	1 PC	595.80	
10 PARKING SENSOR LH	1 PC	491.50	
11 PARKING SENSOR HOLDER	2 PC	56.00	
12 FOGLAMP LH	1 PC	409.20	
13 FOGLAMP CHROME MOULDING LH	1 PC	70.80	
14 FOGLAMP COVER LH	1 PC	41.60	
15 FRONT FENDER COWLING LH	1 PC	265.50	
16 FRONT FENDER COWLING CLIPS	8 PC	25.68	
		4,479.08	
	Less 25%	1,119.77	3,359.31
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
20 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT FENDER LH, SPORTS RIM LHF INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
21 TO SPRAY FRONT BUMPER,FRONT FENDER LH, SPORTS RIM LHF.	1 PC	600.00	
		1,380.00	1,380.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GOH GIAM HWEE
31 FERNVALE ROAD
#12-57
SINGAPORE 797417

ATTN:

Estimate No: MC1901340
Date: 14 Aug 2020
Policy No: PNPV2019-00013778
Veh Reg No: SMK5492T
Make/Model: TOYOTA LEXUS IS250C
A STD

Your Ref No: SMK5492T
Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBE2471K

Estimate Repair Cost to Vehicle No :SMK5492T

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 4,739.31
		Add GST @ 7%	331.75
		Total Amount Payable	S\$ 5,071.06

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVENTY ONE AND CENTS SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	509E

Vehicle Details

Vehicle No.:	SMK5492T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2020
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250C AUTO STD
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	4GR0727605
Chassis No.:	JTHFK252602517722
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$53,007.00
Original Registration Date:	15 Mar 2011
First Registration Date:	15 Mar 2011
Transfer Count:	4
Actual ARF Paid:	\$53,007.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2021
PARF Rebate Amount:	\$26,503.00

Intended COE Rebate Details

COE Expiry Date:	14 Mar 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$75,789.00
COE Rebate Amount:	\$3,976.00
Total Rebate Amount:	\$30,479.00

The information contained herein is correct as at 14 Aug 2020

OK