LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Inspection At

Singapore 079120

51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina Date: 19 Aug 2020

Preliminary Advice

Vehicle No : SLZ663H **Accident Date** : 15/08/2020 Make : MITSUBISHI ATTRAGE Policy No. : 1800042814 **Assignment Date** : 18/08/2020 **Excess** : S\$0.00 Date of Inspection Est. Duration of Repair : 20 : 18/08/2020

> : CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,354.00
Revised Amount	:S\$	29,213.00
Check Items (Estimated)	:S\$	7,475.00
Total	:S\$	36,688.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old \	√alue	:S\$
INCW IOI OIG	v aluc	.Οψ

 Pre-Accident Value
 :S\$ 50,000.00

 COE / PARF Rebate
 :S\$ 32,168.00

Salvage Value :S\$

Margin for Repair :S\$ 17,832.00

Remarks

(.)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Margin for repair is \$ 17,832.00. Repairer proposed repair cost at \$ 22,000.00 to repair the vehicle.