

REP. BY:

REF:

Kenneth

136/ 2000 8595 / Ke

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

MBM

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Got BL

26/8 112pm @ 2050L Carried

Veh No:

SMM 1353C

Yr Regn:

06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make:

Honda

Colour

M. O. Blue

c.c.

1496

Sp. Reading

97758

A/C:

Insured / Std / NI / NA

Eng/No:

T/Radio: Insured / Std / NI / NA

C/No:

RU 1

1319024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

15/8/20

D.O.I.

24/8/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chasals frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Prints

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMM1353C

OUR REF.: SMN3443H

TO: AIG ASIA PACIFIC INSURANCE PTE. LTD.

CC: MOTOR CLAIMS DEPARTMENT

FAX:

*Not Authorized
Resurvey B4pain
L1 Sur @ 2050h 2 days*

DATE: 18/8/2020
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: HONDA VEZEL 1.5X CVT
CHASSIS NO.: RU11319024
ENGINE NO.: L15B5569063
YEAR MADE: 2019
ACCIDENT DATE: 15 August 2020

MATE FOR VEHICLE NO.: SMM1353C

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 1,200.00
2	BONNET CENTER SEAL		1	\$ 100.00
3	FRONT BUMPER 762		1	\$ 990.00
4	FRONT BUMPER LOWER GRILLE		1	\$ 150.00
5	FRONT BUMPER LOWER TRIM		1	\$ 400.00
6	FRONT FOG LAMP LH		1	\$ 250.00
7	FRONT FOG LAMP RH		1	\$ 250.00
8	FRONT BUMPER FOG LIGHT GARNISH RH		1	\$ 105.00
9	FRONT BUMPER FOG LIGHT GARNISH LH		1	\$ 105.00
10	FRONT BUMPER TOWING COVER		1	\$ 60.00
11	FRONT BUMPER LOWER SPOILER (RUBBER)		1	\$ 90.00
12	FRONT BUMPER REINFORCEMENT		1	\$ 600.00
13	FRONT BUMPER RETAINER LH		1	\$ 75.00
14	FRONT BUMPER RETAINER RH 48.60		1	\$ 75.00
15	FRONT BUMPER CLIP		10	\$ 50.00
16	FRONT GRILLE		1	\$ 500.00
17	FRONT GRILLE CHROME MOULDING		1	\$ 400.00
18	FRONT GRILLE (H) EMBLEM		1	\$ 50.00
19	FRONT GRILLE INNER COVER		1	\$ 60.00
20	FRONT GRILLE CLIP		10	\$ 50.00
21	FRONT HEADLAMP LH		1	\$ 1,800.00
22	FRONT HEADLAMP RH		1	\$ 1,800.00
TOTAL:				\$ 9,160.00
LESS 20%:				\$ (1,832.00)
PARTS TOTAL:				\$ 7,328.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SPECIAL NETT

NUMBER PLATE & HOLDER

1 \$ *Sn* 50.00,

BODY SEALANT

1 \$ *nn* 50.00,

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

\$ *2201* 1,600.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ *151* 200.00

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ *nn x* 250.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *2201* 1,000.00

TOTAL: \$ 10,478.00

7% GST: \$ 733.46

GRAND TOTAL: \$ 11,211.46

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W