

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 20 Aug 2020

## **Preliminary Advice**

Insured Vehicle No	: SMA8719Z		
TP Vehicle No	: SLF1661L	Accident Date	: 15/08/2020
Make	: BMW 116D	Assignment Date	: 18/08/2020
Date of Inspection	: 19/08/2020	Est. Duration of Repair	: 14
Inspection At	: EM-1 AUTO PTE LTD (SIN MING) (HQ) 160 SIN MING DRIVE, #05-21 SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front , rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,220.00 labour only
Revised Amount	:S\$	4,460.00 pending part price
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,460.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp