

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang

Date: 03 Sep 2020

Preliminary Advice

Insured Vehicle No : GBG3048H
TP Vehicle No : SLD273R
Make : VOLKSWAGEN POLO GP
Date of Inspection : 19/08/2020
Inspection At : Volkswagen Group Singapore Pte Ltd (tuas) (HQ)
17 Tuas Ave 9
Singapore 639197

Accident Date : 14/08/2020
Assignment Date : 03/09/2020
Est. Duration of Repair : 12 days

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,167.28
Revised Amount	:S\$	18,770.14
Check Items (Estimated)	:S\$	2,137.14
Total	:S\$	20,907.28

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP