

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:22

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016083 Date : 11/03/2021 Order : SLR4875D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLR4875D (V 34741) Regn Date: 16/08/2017 Mileage: 59835 WIP No.: 36787

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V4J1005325 Engine: CHZ 508633 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)


		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5821105A	FENDER Less 020%	1.00	802.00	641.60
X	AN 0161857	POP-RIVET Less 020%	5.00	3.20	12.80
X	A8V0941773D	HEADLIGHT(LAST) Less 020%	1.00	5193.00	4,154.40
X	AWHT006772A	NUT-A/P GT Less 020%	8.00	5.00	32.00
X	AN 91022001	NUT Less 020%	4.00	3.00	9.60

Parts 4,850.40
Labour 0.00
Sublet 2,542.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,392.40

7% GST 517.47

Grand Total 7,909.87



Received by

For & on behalf of
Premium Automobiles Pte Ltd