

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 3 September 2020 2:45 pm
To: Koh, Victor-CK
Cc: SUR
Subject: RE: SKX5405B

Dear Victor,

According to our surveyor, there are 2 clips built into the rear windscreen for attaching the rear windscreen to the rear tailgate. In order to remove the rear windscreen for the replacement of the tailgate, these clips need to be cut and once cut cannot be used back. Hence the rear windscreen was indicated as a necessary item.

For the third brake light, it comes together with the rear windscreen moulding and is also a necessary item once the rear windscreen is removed.

Premium have been instructed to keep these parts and we will forward the supporting photos showing the above in due course.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Monday, 31 August 2020 11:55 am
To: SUR <sur@lkkauto.com>
Subject: SKX5405B

Hi,

Why REAR WINDSCREEN, ADDITIONAL BRAKE LIGHT necessary to replace? photo or part catalogue to justify.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is

accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.