

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 25 Aug 2020

Preliminary Advice

Vehicle No	: SKX5405B	Accident Date	: 09/08/2020
Make	: AUDI A5	Policy No.	: 1800001279
Assignment Date	: 19/08/2020	Excess	: S\$0.00
Date of Inspection	: 19/08/2020	Est. Duration of Repair	: 12
Inspection At	: 24 BENOI SECTOR		
	REPAIRER : PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,970.00
Revised Amount	:S\$	23,966.50
Check Items (Estimated)	:S\$	3,326.00
Total	:S\$	27,292.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	70,861.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,139.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 2,764.00