

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0557/2020/NS 25-Aug-20 Glory Tan 1 OF 1 SKX 5405 B Audi A5 SB 1.8 TFSI MU 8T
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To dislodge and reinstall roof liner to facilitate the renewal of rear lid hinges.	s/n \$ 280.00	
TOTAL		\$ 280.00	

For Premium Automobiles Pte Ltd

Paul
25/08/2020

Authorised Signature

Subject to
insurance approval

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Car-in 21/8/2020.

kiam/keong

10 days

Premium Automobiles

55, 56th Floor, Singapore 408699
Tel: 6346 1123 Fax: 6346 1163

Telefax

wip= 44952

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de</i>	S	2,569.00
2	REAR BUMPER FIXING PARTS ?	S	225.00
3	REAR BUMPER CARRIER ? <i>bt</i>	S	636.00
4	REAR BUMPER BRACKET HOLDER (LH/RH) ? <i>bt</i>	2 S	440.00
5	REAR BUMPER SPOILER <i>see</i>	S	273.00
6	REAR BUMPER GUIDE SECTION - LH / RH UPPER ?	2 S	38.00
7	REAR PARKING AID SENSOR - INNER / OUTER <i>mi</i> / <i>1 pc</i>		TBC
8	REAR BUMPER WIRING SET ?	S	510.00
9	REAR LID <i>bt</i>	S	2,608.00
10	REAR LID ATTACHMENT PARTS ?	S	113.00
* 11	REAR LID HINGE - LH / RH <i>x</i> <i>bt</i>	2 S	452.00
12	REAR LID FLAP GASKET <i>see</i>	S	222.00
13	REAR LID FLAP GASKET - UPPER REAR ?	S	100.00
14	REAR LID STRIKER PLATE ?	S	122.00
15	REAR LID LOCK ? <i>bt</i>	S	169.00
16	LID LOCK PUSH BUTTON ? <i>de</i>	S	172.00
17	PACKING ADHESIVE <i>see</i>	S	18.00
18	GAS FILLED STRUT <i>x</i>	2 S	235.00
19	AUDI EMBLEM <i>see</i>	S	122.00
20	AS INSCRIPTION <i>see</i>	S	95.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 9,119.00

ATI - Rasl

+

Supp.