

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0557/2020/NS

20-Aug-20

Glory Tan

1 OF 1

SKX 5405 B

Audi A5 SB 1.8 TFSI MU 8T

Quantity	Description	Unit Price	Amount
Parts			
1	Rear lid guard plate	\$ 61.00	de ✓
2	Rear lid covver for lock	\$ 8.00	de ✓
3	Cable holder for rear lid trim panel	\$ 45.00	de ✓
Labours			
1	To repair rhs tail lamp panel and lhs tail lamp panel.	\$ 1,200.00	1000
2	To respray rhs tail lamp panel and lhs tail lamp panel. ; RH side fender	\$ 2,000.00	1650
TOTAL		\$ 3,314.00	

add + 2 days for repair
for Mr. 21/8/20.

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

Car-in 21/8/2020.

kiam/keong

10 days

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

wip= 44952

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de</i>	\$	2,569.00
2	REAR BUMPER FIXING PARTS <i>?</i>	\$	225.00
3	REAR BUMPER CARRIER <i>?</i> <i>bt</i>	\$	636.00
4	REAR BUMPER BRACKET HOLDER (LH/RH) <i>?</i> <i>bt</i>	2 \$	440.00
5	REAR BUMPER SPOILER <i>see</i>	\$	273.00
6	REAR BUMPER GUIDE SECTION - LH / RH UPPER <i>?</i>	2 \$	38.00
7	REAR PARKING AID SENSOR - INNER / OUTER <i>mir</i> <i>1pc</i>		TBC
8	REAR BUMPER WIRING SET <i>?</i>	\$	510.00
9	REAR LID <i>bt</i>	\$	2,608.00
10	REAR LID ATTACHMENT PARTS <i>?</i>	\$	113.00
11	REAR LID HINGE - LH / RH <i>X</i>	2 \$	452.00
12	REAR LID FLAP GASKET <i>see</i>	\$	222.00
13	REAR LID FLAP GASKET - UPPER REAR <i>?</i>	\$	100.00
14	REAR LID STRIKER PLATE <i>?</i>	\$	122.00
15	REAR LID LOCK <i>?</i> <i>bt</i>	\$	169.00
16	LID LOCK PUSH BUTTON <i>?</i> <i>de</i>	\$	172.00
17	PACKING ADHESIVE <i>see</i>	\$	18.00
18	GAS FILLED STRUT <i>X</i>	2 \$	235.00
19	AUDI EMBLEM <i>see</i>	\$	122.00
20	A5 INSCRIPTION <i>see</i>	\$	95.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 9,119.00

AIR - Race 1

+

Supp.