

Shirley Hiew (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Tuesday, 25 August 2020 9:52 am
To: Shirley Hiew (LKK Auto)
Subject: FW: Limits Repair for SGJ4253A

Hi Shirley,

This is workshop request amount.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Minoko Chan [mailto:minoko@vermogen-group.com]
Sent: Tuesday, August 25, 2020 8:04 AM
To: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Cc: Pila Ng <pila@vermogen-group.com>; Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; Vmg admin <vmg@vermogen-group.com>; Vermogen Ace <ace@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>
Subject: Re: Limits Repair for SGJ4253A

Dear Sun Pin,

As spoken yesterday , my boss has recommended a repair limit at \$4500.00.

Kindly check & get back to me ASAP.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

Operation Address:

60 Jalan Lam Huat # 03-35/36

Carros Centre Singapore 737869

Tel: 6904 4596

Fax: 6694 4929

Mailing Address:

60 Jalan Lam Huat # 03-35/36

Carros Centre Singapore 737869

On Fri, Aug 21, 2020 at 12:45 PM Minoko Chan <minoko@vermogen-group.com> wrote:

Without Prejudice,

Dear Sun Pin

Please refer to attachment. I checked if this vehicle market value is higher. Kindly base on this market value calculate repair limit & revert. ASAP

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

Operation Address:

60 Jalan Lam Huat # 03-35/36

Carros Centre Singapore 737869

Tel: 6904 4596

Fax: 6694 4929

Mailing Address:

60 Jalan Lam Huat # 03-35/36

Carros Centre Singapore 737869

On Fri, Aug 21, 2020 at 11:22 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Hi Minoko,

Regarding for the vehicle SGJ4253A have repair limits.

The cost for the limits repair is only \$2,000.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

