

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 19/08/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLM6315S
 CHASSIS NO : RU31219018
 MAKE / MODEL : Honda Vezel Hybrid 1.5X CVT
 DATE OF ACCIDENT : 18/08/2020
 YOUR INSURED VEHICLE NUMBER : SKX128J
 MILEAGE : 223712 km

	<u>PARTS DeSCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / PD	1PC	\$ 1,450.00	\$ 1,450.00
3	Rear tailgate Vezel emblem / N/C	1PC	\$ 86.80	\$ 86.80
4	Rear tailgate Honda emblem X	1PC	\$ 81.30	\$ 81.30
5	Rear tailgate Hybrid emblem / N/C	1PC	\$ 86.80	\$ 86.80
5	Rear tailgate windscreen moulding / N/C	1PC	\$ 195.00	\$ 195.00
6	Rear tailgate weatherstrip / PCRU	1PC	\$ 155.00	\$ 155.00
7	Rear tailgate lock / Tum	1PC	\$ 550.00	\$ 550.00
8	Rear tailgate lock catch X	1PC	\$ 180.00	\$ 180.00
9	Rear LH tail lamp / SCR	1PC	\$ 780.00	\$ 780.00
10	Rear LH taillamp reflector / SCR	1PC	\$ 480.00	\$ 480.00
11	Rear end panel / PD	1PC	\$ 830.00	\$ 830.00
12	Rear end panel top garnish / CRU	1PC	\$ 155.00	\$ 155.00
13	Rear bumper / CRU	1PC	\$ 955.00	\$ 955.00
14	Front bumper / CRU	1PC	\$ 955.00	\$ 955.00
			LIST TOTAL S\$:	\$ 5,984.90
			20.00% DISCOUNT S\$:	\$ 1,196.98
				\$ 4,787.92

Rear floor panel / CRU
 buzzer ?

photo

SPECIAL NETT

1	Rear bumper clips	1 SET	\$	80.00	30
2	End panel top garnish clips	1 SET	\$	80.00	20
3	Reverse sensor	1 SET	\$	240.00	200
4	Front bumper clips	1set	\$	80.00	30
5	Windscreen sealant	1PC	\$	200.00	50
Special Nett Total S\$:			\$	680.00	

LABOUR CHARGES

1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts	\$	1,200	1,000
2	To labour charge for removing front bumper out to facilitate replacement of damaged parts	\$	400.00	250
3	To respray front bumper	\$	400.00	200
4	To respray rear tailgate, end panel and spare tyre panel, front bumper	\$	800.00	
5	To remove and install rear tailgate glass	\$	160.00	120
6	To apply rustproofing on all damaged parts	\$	180.00	60
7	To check wiring system	\$	100.00	30
	To activate and deactivate high voltage hybrid battery as a safety precaution	\$	300.00	
6	To conduct a standard of opening procedures post repairs scan test as a requirements upon completion of collision repairs	\$	300.00	350

LABOUR TOTAL S\$:	\$	3,540.00
TOTAL S\$:	\$	9,007.92
7% GST	\$	630.55
GRAND TOTAL S\$:	\$	9,638.47

Repair day - 8 days

4/5
After paint photo

Sun Bn (LKR)

14/08/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: