



TRANS EUROKARS PTE LTD

LKK
EUROKARS GROUP

ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Eurokars Leasing ADDRESS: 12 Sungel Kadut Ave Spore 729648 TEL: 88685085		WIP: 33813 EXCESS: DATE: 18-Aug-20	
VEH NO:	SKS225M	DATE IN:		CONTACT PERSON:	Ronald 63957875
CHASSIS NO:	JM6CC1071E0103543	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	BIANTE	DATE REG.:	12-Mar-14	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER / DD	1	MC275-50-221FB8		\$ 1,170.50
2	GROMMET, REAR BUMPER / MC	2	MB01W-51-142B		\$ 6.40
3	PIN LOCATOR, REAR BUMPER / MC	2	MGJ6B-50-1K5		\$ 8.40
4	GROMMET, REAR BUMPER / MC	2	MBP4K-50-ES1		\$ 9.40
5	RIVET, REAR BUMPER / MC	2	MA001-50-7C1		\$ 7.60
6	FASTENER, REAR BUMPER / MC	2	MGD7A-50-EA1		\$ 6.40
7	TAPE PROTECTOR, REAR BUMPER / MC	2	MTK48-62-864		\$ 14.80
8	STRIPE LHS, REAR BUMPER / MC	1	MC467-50-888		\$ 86.00
9	STRIPE RHS, REAR BUMPER / MC	1	MC467-50-878		\$ 86.00
10	STRIPE CENTER, REAR BUMPER / MC	1	MC467-50-879		\$ 130.10
11	TAILGATE / DD	1	MC2Y3-62-02XF		\$ 1,699.70
12	VALVE ONEWAY, TAILGATE / MC	2	MBBN7-58-867		\$ 27.60
13	FASTENER, TAILGATE / MC	3	MB467-68-AC3 34		\$ 16.80
14	FASTENER, TAILGATE / MC	3	MEG21-51-146		\$ 18.60
15	ORNAMENT, SKYACTIV / MC	1	MC603-51-771A		\$ 117.10
16	FASTENER, REAR WINDSCREEN / MC	4	MD204-50-896A		\$ 11.20
17	SPACER, REAR WINDSCREEN / MC	5	MGJ6A-50-897		\$ 64.00
18	FASTENER, REAR WINDSCREEN / MC	2	MC273-50-896		\$ 16.40
19	REAR END PANEL / DD	1	MC273-70-750B		\$ 303.20
TOTAL PARTS					\$ 3,800.20
TOTAL PARTS COST					\$ 3,800.20
Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 60			2640 \$ 3,630.00

2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE. <i>670</i>	<i>1890</i>	\$ 2,520.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NETT	\$ 180.00 ✓
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	<i>330</i>	\$ 660.00
5	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00 ✓
6	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00 ✓
7	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	<i>200</i>	\$ 330.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)	<i>330</i>	\$ 660.00
9	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.(WITH REVRSE CAMERA)	<i>330</i>	\$ 660.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	\$ 70.00 X
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150</i>	\$ 250.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>120</i>	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>180</i>	\$ 350.00
14	MZ-BR-SUNDRI	SUNDRIES. <i>20</i>	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 10,340.00
TOTAL PARTS	\$ -	\$ 3,800.20
TOTAL	\$ -	\$ 14,140.20
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED

ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
the PRICE AS WELL AS LABOUR CHARGES.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized Signature

Steve (LKK)
8322 8813

sterechn@lkk.com

with Peril
21/8/20, 3.00pm

P/P

By Bel spy
9 days

TRANS EUROKARS PTE LTD

	SUPPLEMENTARY ITEMS				
1	LHR TRIM, TRUNK X NN	1	MC273-68-870F56	\$ 632.70	\$ 632.70
2	FINISHER, TAILGATE ✓ BR	1	MC273-50-850L	\$ 2,018.60	\$ 2,018.60
3	LH TAIL LAMP ✓ BR	1	MC273-51-160E	\$ 1,117.20	\$ 1,117.20
4	TRIM, END PANEL ✓ CUT	1	MC273-68-89XA56	\$ 122.30	\$ 122.30
5	SHORT CORD ✓ BR	1	MC273-67-SH2	\$ 74.90	\$ 74.90
6	ANTENNA & KEYLESS BRACKET ✓ BR	1	MC277-67-6N0	\$ 265.80	\$ 265.80

TRANS EUROKARS PTE LTD

Authorised Signature