

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 31 Aug 2020

Preliminary Advice

Insured Vehicle No : GBJ6237T

TP Vehicle No : SKP3363T

Make : BMW 320I

Date of Inspection : 24/08/2020

Inspection At : Super Zee Motor Service (HQ)
BLK 14 DEFU LANE 10 #01-402
Singapore 539195

Accident Date : 18/08/2020

Assignment Date : 28/08/2020

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,985.35
Revised Amount	:S\$	2,511.87
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,511.87
Lump Sum Repair	:S\$	2,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP