



STI INSURANCE PTE LTD  
27A TANJONG PENJURU, SINGAPORE 609042  
ESTIMATE COST OF REPAIRS

(S) FIRE & MARINE

|                                                                                               |                                                                                                                                                              |                                                                         |                  |                                          |              |
|-----------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|------------------|------------------------------------------|--------------|
| INDIA INT'L INSURANCE PTE LTD<br>65 CECIL STREET #04-05<br>ROBIN BUILDING<br>SINGAPORE 049711 |                                                                                                                                                              | NAME: Tang Wee Houe<br>ADDRESS: 2B Bukit Timah Road<br>Singapore 309121 |                  | VIR: 67786<br>EXCESS:<br>DATE: 14 May 20 |              |
| ATTN: MOTOR CLAIMS<br>FAX:                                                                    |                                                                                                                                                              | TEL:                                                                    |                  |                                          |              |
| VEH NO: SDG8710Y                                                                              | DATE IN:                                                                                                                                                     | CONTACT PERSON:                                                         | TYPE:            | REMARKS:                                 |              |
| CHASSIS NO: WPD2229R215600411                                                                 | MILEAGE:                                                                                                                                                     | TYPE OF CLAIM:                                                          | THIRD PARTY      |                                          |              |
| MODEL: 986 ROSSIER TIPTRONIC                                                                  | DATE REG: 5 Jan 01                                                                                                                                           | POLICY NO:                                                              |                  |                                          |              |
| NATURE OF WORKS                                                                               |                                                                                                                                                              |                                                                         |                  |                                          |              |
| S/NO                                                                                          | Parts Description                                                                                                                                            |                                                                         | QTY              | REMARKS                                  | PRICE        |
| 1                                                                                             | FRONT FENDER RH                                                                                                                                              |                                                                         | 1                | P996 503 032 0A GRN                      | 1,225.00     |
| 2                                                                                             | SPEED NUT                                                                                                                                                    |                                                                         | 11               | P999 507 003 01                          | 27.50        |
| 3                                                                                             | FRONT RH FENDER COVER                                                                                                                                        |                                                                         | 1                | P996 504 642 01 OLC                      | 25.50        |
| 4                                                                                             | RIVET                                                                                                                                                        |                                                                         | 3                | P999 531 712 40                          | 4.50         |
| 5                                                                                             | PROTECTIVE FILM RH                                                                                                                                           |                                                                         | 1                | P996 504 532 00                          | 25.25        |
| 6                                                                                             | FRONT RH FENDER STRUT BAR                                                                                                                                    |                                                                         | 1                | P996 504 441 00 GRN                      | 52.25        |
| 7                                                                                             | FRONT FENDER BRACKET                                                                                                                                         |                                                                         | 1                | P996 504 555 00 GRN                      | 22.25        |
| 8                                                                                             | HEXAGON NUT                                                                                                                                                  |                                                                         | 6                | P900 377 010 01-                         | 3.50         |
| 9                                                                                             | FRONT BUMPER                                                                                                                                                 |                                                                         | 1                | P986 505 311 07-                         | 1,317.00     |
| 10                                                                                            | FRONT BUMPER TOWING COVER                                                                                                                                    |                                                                         | 1                | P964 505 103 00 G2X                      | 37.40        |
| 11                                                                                            | FRONT BUMPER RETAINER RH                                                                                                                                     |                                                                         | 1                | P996 505 536 00-                         | 113.25       |
| 12                                                                                            | BRACKET-RETAINING STRIP FRT BPR RH                                                                                                                           |                                                                         | 1                | P996 505 540 00                          | 32.50        |
| 13                                                                                            | RHS MIRROR HOUSING                                                                                                                                           |                                                                         | 1                | P996 731 620 00 G2L                      | 242.25       |
| 14                                                                                            | MIRROR BASE RIGHT ELECTRIC                                                                                                                                   |                                                                         | 1                | P996 731 220 03 G2L                      | 632.50       |
| 15                                                                                            | TRIM SIDE MIRROR RH                                                                                                                                          |                                                                         | 1                | P996 731 720 00 G2L                      | 22.40        |
| 16                                                                                            | MIRROR ADJUSTING MOTOR                                                                                                                                       |                                                                         | 1                | P996 624 048 00 jammed                   | 329.00       |
| 17                                                                                            | FILLER PIECE OUTER RH                                                                                                                                        |                                                                         | 1                | P996 537 732 00                          | 35.10        |
| 18                                                                                            | FILLER PIECE INNER RH                                                                                                                                        |                                                                         | 1                | P996 537 734 00                          | 24.00        |
| 19                                                                                            | MIRROR GLASS (6678)                                                                                                                                          |                                                                         | 1                | P996 731 036 02-                         | 272.40       |
| 20                                                                                            | FRONT RH SIGNAL LIGHT                                                                                                                                        |                                                                         | 1                | P996 631 034 03-                         | 122.00       |
| 21                                                                                            | SHOCK ABSORBER RH                                                                                                                                            |                                                                         | 1                | P986 343 041 23-                         | 1,435.00     |
| 22                                                                                            | FRT ABSORBER STOPPER                                                                                                                                         |                                                                         | 1                | P996 343 301 02-                         | 60.10        |
| 23                                                                                            | DEEP-GROOVE BALL BEARING W                                                                                                                                   |                                                                         | 1                | P996 343 515 05-                         | 114.10       |
| 24                                                                                            |                                                                                                                                                              |                                                                         | 0                | 0                                        | -            |
| Supp                                                                                          |                                                                                                                                                              |                                                                         |                  |                                          |              |
| Frt fender wheel arch                                                                         |                                                                                                                                                              | de ✓                                                                    | TOTAL PARTS      |                                          | 4,738.50     |
| wing front cap lid                                                                            |                                                                                                                                                              | can ✓                                                                   | LESS 10%         |                                          | 442.70       |
| Retrol filler rock bracket                                                                    |                                                                                                                                                              | de ✓                                                                    | TOTAL PARTS COST |                                          | 4,295.80     |
|                                                                                               |                                                                                                                                                              |                                                                         |                  |                                          | 3,223        |
|                                                                                               |                                                                                                                                                              |                                                                         |                  |                                          | 3,562.00     |
|                                                                                               |                                                                                                                                                              |                                                                         |                  |                                          | 10% - 240.97 |
|                                                                                               |                                                                                                                                                              |                                                                         |                  |                                          | 3,205.80     |
| Labour Description                                                                            |                                                                                                                                                              |                                                                         |                  |                                          |              |
| 1                                                                                             | TO REMOVE /INSTALL FRT BUMPER, FRT FENDER RH, RH SIDE MIRROR & ALL ACCIDENT DAMAGED BODY PARTS TO REPAIR FRONT DOOR RH & ALL AREAS AFFECTED BY THE ACCIDENT. |                                                                         |                  | 4680 ✓                                   | 6,240.00     |
|                                                                                               |                                                                                                                                                              |                                                                         |                  | 1560                                     |              |

|         |                                                                          |           |             |
|---------|--------------------------------------------------------------------------|-----------|-------------|
| Regn: 2 | TO RESPRAY FRT BUMPER, FRT FENDER RH, FRT DOOR RH, RH SIDE MIRROR RH.    | 13750     | \$ 4,600.00 |
| 3       | TO CARRY-OUT BODY CAVITY PRESERVATION.                                   | 200       | \$ 250.00   |
| 4       | TO REMOVE & REPLACE THE FRONT SUSPENSION RH                              | NETT 8 hr | \$ 1,560.00 |
| 5       | TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. <i>Report</i> | NETT 8 hr | \$ 680.00   |
| 6       | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                       | 200 ✓     | \$ 250.00   |
| 7       | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                          | NETT ✓    | \$ 600.00   |
| 8       | SUNDRIES.                                                                | NETT 20 ✓ | \$ 50.00    |
|         |                                                                          |           | 9450        |

|                    |      |              |
|--------------------|------|--------------|
| TOTAL LABOUR       | \$ - | \$ 14,230.00 |
| TOTAL PARTS        | \$ - | \$ 6,222.06  |
| TOTAL              | \$ - | \$ 20,452.06 |
| LESS EXCESS        | \$ - | \$ -         |
| TOTAL AFTER EXCESS | \$ - | \$ -         |
| GST 7%             | \$ - | \$ -         |
| GRAND TOTAL        | \$ - | \$ -         |

# REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

3,205.80

~~2909.30~~

9450

\$12,655.80

6 days #

Tanpin 97895749 / 67418451

wp  
21/8/2021 am

06 days

Resurvey before paint  
tanpin@lkk.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: