



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

24-Aug-2020

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Honda NF125MD-125CC - FU8814J

1pc of Head Lamp <i>SCA</i> ✓	S\$	55.00	
1pc of Front Signal Light <i>X Svc</i>		45.00 X	
1pc of Handle Bar <i>X Svc</i>		48.00 X	
1pc of Front Fork Complete <i>bt</i> ✓		320.00	
1pc of Mirror <i>SCA</i> ✓		25.00	
1pc of Body Set <i>SCA</i> ✓		280.00	
1pc of Front Brake Shoe Pump <i>X Svc</i>		160.00 X	
1pc of Front Brake Disc <i>X Svc</i>		65.00 X	
1pc of Front Sport Rim <i>X Svc</i>		165.00 X	
1pc of Clutch Cover <i>SCA</i> ✓		68.00	
1pc of Front Footrest <i>bt</i> ✓		35.00	
1pc of Rear Footrest <i>SCA</i> ✓		15.00	
1pc of Footrest Bracket <i>bt</i> ✓		43.00	
1pc of Exhaust Pipe <i>X Svc</i>		215.00 X	
1pc of Front Mudguard <i>SCA</i> ✓		35.00	
		<u>1,574.00</u>	
		Less 10%	
		157.40	
		<u>1,416.60</u>	
		Transport	30.00 ✓
		IU	165.00 <i>cm</i> ✓
		Engine Oil	15.00 <i>X an</i> ✓
		Gasket	12.00 <i>X an</i> ✓
		Rear Box	90.00 <i>SCA</i> ✓
		Steering Cone	65.00 <i>rec</i> ✓
		Labour	250.00 <i>200</i> ✓
		<u>\$2,043.60</u>	

876
109
788.40

Ram
4p 90010368
3 days
48
20/08/2020
@ 1740
Repair after repair

Yours Faithfully,
Southern Motor

Ng

48-1,050
3 days

788.40
550.00
1338.40
209
1070.72