

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Hp 96699986


INVOICE

Mr. Lau Jiunn Min
Block 722 Tampines Street 72 #13-13
Tampines Starlight
Singapore 520722

Invoice No : PA/20060004/tpw
Our Ref : PA/FBJ6607/1119/tpw
Date : 09 June 2020

Claim Type	Third Party	Date of Accident	13 November 2019
Vehicle No.	FBJ 6607 J	Date of Inspection	15 November 2019
No	Description	Amount (S\$)	
1	Survey fees inclusive of Transportation and Photographs (31) copies	\$511.00	
Total			\$511.00
Singapore Dollar: Five Hundred And Eleven Only			
All payments made payable to : Prudent Adjustors Services			

21/08/2020 - To submit 4/5 1850/-
with 2 days.


Prudent Adjustors Services
Bok Jee Tan

- Exhaust unlikely to be damaged.

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Lau Jiunn Min
Block 722 Tampines Street 72 #13-13
Tampines Starlight
Singapore 520722

Our Ref : PA/FBJ6607/1119/tpw
Date : 09 June 2020

REFERENCES

Claim Type	: Third Party	Date of Accident	: 13 November 2019
Vehicle No.	: FBJ 6607 J	Date of Assignment	: 15 November 2019
Make	: Yamaha	Date of Inspection	: 15 November 2019
Model	: FJR1300A	Date of Re-inspection	: 17 Feb & 02 Mar 2020
Reg. Date	: 27 August 2014	COE Expiry	: 26 August 2024
Color	: Black	Chassis No	: JYARP231000002877
Odometer	: 88,292 km	Engine No	: Blocked

TYRE CONDITION

	Make	Size	Thread Balance
Front	Bridgestone	120/70-17	5mm
Rear	Michelin	180/55-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and left side portion.
Please refer to photographs and assessment of repairs for details
Enclosed (31) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$5,354.89 Revised Assessment \$4,100.00 Lump sum

Survey conducted at Ong Motor Trading

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Five (5) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES


Vehicle No: **FBJ 6607 J**

Our Ref: **PA/FBJ6607/1119/tpw**

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation	
1	Saddlebag LH	1 pc	Cut	1,848.00	1,848.00	✓
2	Saddlebag bracket LH	1 pc	Bent	374.40	374.40	HH
3	Muffler assy LH	1 pc	Cut/bent	2,287.20	2,287.20	HH
4	Front footrest LH	1 pc	Cut	162.50	162.50	✓
5	Engine guard cover LH	1 set	Cut	300.00	300.00	✓
				4,972.10	4,972.10	
	List price less 10%	2310.50		497.21	497.21	
		2079.45		4,474.89	4,474.89	
	<u>Special Nett Items</u>					
6	Saddle bag emblem	1 pc	Necessary	80.00	80.00	✓
		80.00				
	<u>Labour Charges</u>					
	Align body and sub frame			350.00	280.00	HH
	Workmanship to repair, renew damaged areas	200.00		450.00	300.00	200/-
				800.00	580.00	
	Total parts & labour concluded			<u>5,354.89</u>	<u>5,134.89</u>	
	Lump sum repair adjustment	2359.45			<u>4,100.00</u>	
		4/5 1850/-	2 days			

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 577D

Vehicle Details

Vehicle No.: FBJ6607J
Vehicle to be Exported: Yes
Intended Deregistration Date: 15 Nov 2019
Vehicle Make: YAMAHA
Vehicle Model: FJR1300 A
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: P516E006982
Chassis No.: JYARP231000002877
Maximum Power Output: -
Open Market Value: \$12,990.00
Original Registration Date: 27 Aug 2014
First Registration Date: 27 Aug 2014
Transfer Count: 5
Actual ARF Paid: \$1,949.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Aug 2024
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$4,354.00
COE Rebate Amount: \$2,084.00
Total Rebate Amount: \$2,084.00

The information contained herein is correct as at 15 Nov 2019

OK