

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Aug 2020		21 Aug 2020 14:41 Edit Adj Rpt	S\$814.30 Edit Estimates	S\$814.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: DE COSTA RICHARD BOB , ID: S1685452B, GST No.: NO, Tel: +6597527330, Email: DECOSTARICHARD@YAHOO.COM									
Main Claimant: JURAIMI BIN OMAR , ID: S8741204J									
Vehicle Reg. No.:	F1093T	Date of Loss:	14/08/2020 20:00 - :59 [3 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 246812	Policy/Cover Note No.:	1001405226 (Comprehensive) Coverage: 23/05/2020 - 22/05/2021						
Vehicle Reg. No. (Insured):	SLC6703H	Policy No. (Claimant):	AN3183753						
		Excess:	S\$0.00						
Repairer:	Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558, 539187 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/09/2020]								
Driver/Custodian (Insured):	DE COSTA RICHARD BOB (55 / Male), NRIC: S1685452B, Tel: +6597527330 Email: DECOSTARICHARD@YAHOO.COM								
Adj Asg. Remarks:	Please arrange survey by today. on WP. Please contact us ASAP if you cannot attend. Liab: Clear. Assign: IHS. Contact: Shuqi @ 6283 5474								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (21/08/2020): Cancellation of Assignment: F1093T									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***F1093T (246812)**
[SLC6703H]
TP
JURAIMI BIN OMAR
Aug 14 2020 8:00PM
[DE COSTA RICHARD BOB]
Teo Spray Painting

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	20/08/20 08:49	Accident Statement From:OD - Reg. No: SLC6703H, Claimant: Richard Bob De Costa		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/08/20 17:05	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail Print
1	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
2	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
3	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
4	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
5	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
6	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
7	17/08/20 17:10	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
8	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
9	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
10	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
11	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
12	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
13	17/08/20 17:23	SCENE PHOTO [Linked Accident Report Documents]		Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/08/20 18:16	General View		Load JPG ☒
2	21/08/20 18:16	General View		Load JPG ☒
3	21/08/20 18:16	General View		Load JPG ☒
4	21/08/20 18:16	General View		Load JPG ☒
5	21/08/20 18:16	Chassis Number		Load JPG ☒
6	21/08/20 18:16	General View		Load JPG ☒
7	21/08/20 18:16	General View		Load JPG ☒
8	21/08/20 18:16	General View		Load JPG ☒
9	21/08/20 18:16	General View		Load JPG ☒
10	21/08/20 18:16	General View		Load JPG ☒
11	21/08/20 18:16	General View		Load JPG ☒
12	21/08/20 18:16	General View		Load JPG ☒
13	21/08/20 18:16	General View		Load JPG ☒
14	21/08/20 18:16	General View		Load JPG ☒
15	21/08/20 18:16	General View		Load JPG ☒
16	21/08/20 18:16	General View		Load JPG ☒
17	21/08/20 18:16	General View		Load JPG ☒

Assessment Reports				1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
18	21/08/20 18:16	General View		Load JPG	☒
19	21/08/20 18:16	General View		Load JPG	☒
20	21/08/20 18:16	General View		Load JPG	☒
21	21/08/20 18:16	General View		Load JPG	☒
22	21/08/20 18:16	General View		Load JPG	☒
23	21/08/20 18:16	General View		Load JPG	☒
24	21/08/20 18:16	General View		Load JPG	☒
25	21/08/20 18:16	General View		Load JPG	☒
26	21/08/20 18:16	General View		Load JPG	☒
27	21/08/20 18:16	General View		Load JPG	☒
28	21/08/20 18:16	General View		Load JPG	☒
29	21/08/20 18:16	General View		Load JPG	☒
30	21/08/20 18:16	General View		Load JPG	☒
31	21/08/20 18:16	Odometer Reading		Load JPG	☒
32	21/08/20 18:16	General View		Load JPG	☒
33	21/08/20 18:16	General View		Load JPG	☒
34	21/08/20 18:16	General View		Load JPG	☒
35	21/08/20 18:16	General View		Load JPG	☒
36	21/08/20 18:16	General View		Load JPG	☒
37	21/08/20 18:16	General View		Load JPG	☒
38	21/08/20 18:16	General View		Load JPG	☒
39	15/09/20 17:39	Reinspection Photo		Load JPG	☒
40	15/09/20 17:39	Reinspection Photo		Load JPG	☒
41	15/09/20 17:39	Reinspection Photo		Load JPG	☒
42	15/09/20 17:39	Reinspection Photo		Load JPG	☒
43	15/09/20 17:39	Reinspection Photo		Load JPG	☒
44	15/09/20 17:39	Reinspection Photo		Load JPG	☒
45	15/09/20 17:39	Reinspection Photo		Load JPG	☒
46	15/09/20 17:39	Reinspection Photo		Load JPG	☒
47	15/09/20 17:39	Reinspection Photo		Load JPG	☒
48	15/09/20 17:39	Reinspection Photo		Load JPG	☒
49	15/09/20 17:39	Reinspection Photo		Load JPG	☒
50	15/09/20 17:39	Reinspection Photo		Load JPG	☒
51	15/09/20 17:39	Reinspection Photo		Load JPG	☒
52	15/09/20 17:39	Reinspection Photo		Load JPG	☒
53	15/09/20 17:39	Reinspection Photo		Load JPG	☒
54	15/09/20 17:39	Reinspection Photo		Load JPG	☒
55	15/09/20 17:39	Reinspection Photo		Load JPG	☒
56	15/09/20 17:39	Reinspection Photo		Load JPG	☒
57	15/09/20 17:39	Reinspection Photo		Load JPG	☒
58	15/09/20 17:39	Reinspection Photo		Load JPG	☒
59	15/09/20 17:39	Reinspection Photo		Load JPG	☒
60	15/09/20 17:39	Reinspection Photo		Load JPG	☒
61	15/09/20 17:39	Reinspection Photo		Load JPG	☒
62	15/09/20 17:39	Reinspection Photo		Load JPG	☒
63	15/09/20 17:39	Reinspection Photo		Load JPG	☒
64	15/09/20 17:39	Reinspection Photo		Load JPG	☒
65	15/09/20 17:39	Reinspection Photo		Load JPG	☒
66	15/09/20 17:39	Reinspection Photo		Load JPG	☒
67	15/09/20 17:39	Reinspection Photo		Load JPG	☒
68	15/09/20 17:39	Reinspection Photo		Load JPG	☒
69	15/09/20 17:39	Reinspection Photo		Load JPG	☒
70	15/09/20 17:39	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
71	15/09/20 17:39	Reinspection Photo		Load JPG	☒
72	15/09/20 17:39	Reinspection Photo		Load JPG	☒
73	15/09/20 17:39	Reinspection Photo		Load JPG	☒
74	15/09/20 17:39	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/08/20 17:21	Sketch Plan [Linked Accident Report Documents]		Load JPG	☒
2	17/08/20 17:21	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	☒
3	17/08/20 17:22	Identification Card [Linked Accident Report Documents]		Load JPG	☒
4	17/08/20 17:22	Driving License [Linked Accident Report Documents]		Load JPG	☒
5	17/08/20 17:22	Common Statement [Linked Accident Report Documents]		Load JPG	☒
6	17/08/20 17:22	Individual Statement [Linked Accident Report Documents]		Load JPG	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/08/20 13:38	TPD F1093T GIA REPORT		Load PDF	
2	21/08/20 13:38	TPD F1093T - ESTIMATE REPAIR		Load PDF	
3	21/08/20 13:38	TPD F1093T - PRI		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/08/20 17:33	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/08/20 17:10	Accident Photo		Load JPG	☒
2	17/08/20 17:10	Accident Photo		Load JPG	☒
3	17/08/20 17:10	Accident Photo		Load JPG	☒
4	17/08/20 17:10	Accident Photo		Load JPG	☒
5	17/08/20 17:10	Accident Photo		Load JPG	☒
6	17/08/20 17:10	Accident Photo		Load JPG	☒
7	17/08/20 17:10	Accident Photo		Load JPG	☒
8	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
9	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
10	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
11	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
12	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
13	17/08/20 17:23	SCENE PHOTO		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/08/20 17:21	Sketch Plan		Load JPG	☒
2	17/08/20 17:21	Sketch Plan #2		Load JPG	☒
3	17/08/20 17:22	Identification Card		Load JPG	☒
4	17/08/20 17:22	Driving License		Load JPG	☒
5	17/08/20 17:22	Common Statement		Load JPG	☒
6	17/08/20 17:22	Individual Statement		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20008813/ESF3S2**Date:** 22/09/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001405226
Claimant Vehicle No :	F1093T	Insured Vehicle No :	SLC6703H
Date of Loss:	14/08/2020	Nature of Claim:	TP
		Claim No:	246812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	F1093T	Engine No:	G3J6E0271872
Make & Model:	YAMAHA XSR155 MANUAL, 155cc	Chassis No:	MH3RG4760LK005997
Reg. Date:	27/04/2020 (Man. Year: 2020)	Odometer:	3713 km
Colour:	Silver		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	4.00-17	Rear Tyre Size:	4.50-17
Front Left Side:	Swallow 5 mm	Rear Left Side:	Swallow 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	594.00	564.30	29.70	5.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	320.00	250.00	70.00	21.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	914.00	814.30	99.70	10.91

INSPECTION

Date of Assignment:	21/08/2020	Teo Spray Painting (HQ)
Date Inspected:	21/08/2020 Inspected At:	BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558
Estimated Period of Repair:	3.0 days	Singapore 539187

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Sep 2020)	
Parts:	N/A	YAMAHA XSR155 MANUAL 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for F1093T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	78.00 FL	*78.00 FL
2	1		*CLUTCH LEVER	Bent	28.00 FL	*28.00 FL
3	1		*HANDER GRIPS	Torn	38.00 FL	*30.00 FL
4	1		*RADIATOR	Bent	320.00 FL	*295.00 FL
5	1		*COOLAND	Necessary	18.00 FL	*18.00 FL
6	1		*FRONT FENDER	Bent	78.00 FL	*78.00 FL
7	1		*FRONT FOOTREST LH	Broken	25.00 FL	*25.00 FL
8	1		*FRONT FOOTREST BRACKET LH	Bent	75.00 FL	*75.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	660.00	627.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	66.00	62.70
Total Parts (\$\$)	594.00	564.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT.	New	70.00	50.00
2	LABOUR CHARGES.	New	250.00	200.00
Gross Labour Cost (S\$)			320.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >