



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC20005621/Gqf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date : 27-08-2020



ATTN: NATALIE LEE

Code : INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 499J	Veh. Inspected	SDP 92C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/CA/TP/036/1092550-001/NL	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	13/07/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD1173422N093951	Colour	WHITE
Odometer	136058	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	PIRELLI	5 mm
L/H Front Tyre	225/40 R18	PIRELLI	5 mm
R/H Rear Tyre	225/40 R18	PIRELLI	5 mm
L/H Rear Tyre	225/40 R18	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/05/2020	Inspection Date	11/05/2020
Survey held at	KIAN TEONG AUTO CENTRE BLK 176 SIN MING DRIVE #01-08 SIN MING CARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------