

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005993

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

-

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 21/08/2020

ACCIDENT DATE : 21/07/2020

VEHICLE NO : SJS9206X

CHASSIS/ENG.NO : MR053HY9305128680

VEHICLE MODEL : TOYOTA VIOS

CLAIM NO : D20002998MFSH

POLICY NO :

REMARK 9206 FIRST CAP TP
AGST SHC7298B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	495.70	25	371.77	371.77
SUB-TOTAL:							371.77
** NETT PRICE **							
1	10	PC	REAR BUMPER CLIPS	4.00	10	3.60	36.00
SUB-TOTAL							36.00
** WORK LABOUR **							
			TO KNOCK REAR FENDER RH,WELD,REMOVE & REPLACE ABOVE PARTS			400.00	400.00
			TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS			500.00	500.00
SUB-TOTAL							900.00

JOYCE

PAGE: 1 of 1

SUB-TOTAL : S\$ 1,307.77

ADD 7% GST. S\$ 91.54

GRAND TOTAL : S\$ 1,399.31

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.