



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20008885/Ksf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 04-09-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 2731A	Veh. Inspected	SMN 2753U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002457/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	24/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800393085	Colour	METALLIC GREY
Odometer	58127	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	5 mm
L/H Front Tyre	225/45 R17	MICHELIN	5 mm
R/H Rear Tyre	225/45 R17	MICHELIN	8 mm
L/H Rear Tyre	225/45 R17	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/08/2020	Inspection Date	25/08/2020
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------