Shirley Hiew (LKK Auto)

From: Simon Ho (LKKAuto)

Sent: Friday, 4 September 2020 11:18 am

To: Shirley Hiew (LKK Auto)

Subject: Re: SKA 7103E DOA - 25/01/2019

Hi Shirley,

Audit check done for SKA7103E, found spray painting labour too low for 2 panels. I already told Guo Qiang to adjust.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561| email: simonho@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The lated large current for displays. The filtering hazardern reveal, streaming, or deleted, lately find the late principle for contributions of the latest principle for contributions of the latest

Save the Earth. Print only when necessary.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Friday, 4 September 2020 10:35 AM

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: SKA 7103E DOA - 25/01/2019

Hi Simon,

Kindly check the paper survey report and let me know whether can I submit this report.

Documents Uploaded in Views.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.