

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page

1/2

Mr
PNG
SZE YAN, BERNIE
7 BOON KENG ROAD
#01-132
Singapore 330007

Document no.
Document date 25-08-2020
Customer no. 5211019114
Customer GST-ID
Dealer 30001
Job order number 2020019966/ 1
Job order date 24-08-2020
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SKF3860C	5K13G5	24-05-2012	WVWZZZ1KZCW297297	Golf 1.4 Comfo 90 TSI D7F	121

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00 X	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5K2941006K	Twin Halogen Headlamps <i>scu</i>	1	pcs.	725.37	#1	725.37	776.15
6R0973735	Flat Contact Housing <i>3?</i>	1	pcs.	19.19	#1	19.19	20.53
	H/LAMP WIRE HOUSING <i>de</i>						
5K0807217BLGRU	Cover For Bumper Primed	1	pcs.	1,210.37	#1	1,210.37	1,295.10
5K0805903A 9B9	Spoiler Satin Black <i>?</i>	1	pcs.	296.47	#1	296.47	317.22
5K0807724B	Support Part <i>3?</i>	1	pcs.	27.36	#1	27.36	29.28
	BUMPER INNER BRACKET RH						
5K0807228A	Guide Piece <i>3?</i>	1	pcs.	36.24	#1	36.24	38.78
	(RHS H/Lamp lower bracket) <i>3?</i>						
5K0807572J	Guide Piece <i>3cm</i>	1	pcs.	118.81	#1	118.81	127.13
	(RHF bumper bracket)						
5K6821022B	Fender <i>3</i>	1	pcs.	615.49	#1	615.49	658.57
5K6821136	Cross Support <i>3</i>	1	pcs.	31.68	#1	31.68	33.90
	FENDER BRACKET RH <i>3</i>						
5K0805978	Wheelhouse Liner <i>3 scu</i>	1	pcs.	168.19	#1	168.19	179.96
	(RHS Fender Liner Upper)						
5K0805912B	Wheelhouse Liner <i>3X</i>	1	pcs.	123.98	#1	123.98	132.66
	(RHF Fender Liner lower)						
5K0853651AMZLL	Radiator Grille Satin Bla <i>X</i>	1	pcs.	620.02	#1	620.02	663.42
5K0853666 9B9	Cooling Air Grill Satin B <i>3 mis</i>	1	pcs.	111.98	#1	111.98	119.82
	FOG LAMP GRILLE RH						
5K0853102 2ZZ	Decorative Moulding Chrom <i>3X mis</i>	1	pcs.	67.42	#1	67.42	72.14
	FOG LAMP GRILLE CHROME RH						
5K0941700F	Halogen Fog Lights With S <i>cm</i>	1	pcs.	262.89	#1	262.89	281.29
	LABOUR	5	pcs.	840.00	#1 <i>1680</i>	4,200.00	4,494.00
	SPRAY PAINTING	5	pcs.	800.00	#1 <i>2400</i>	4,000.00	4,280.00

Quotation valid till 31-08-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	12,635.46	7%	937.68	13,395.46	14,333.14

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial
Vehicles

Quotation

Non binding - Preview

Page 2/2

Mr
PNG
SZE YAN, BERNIE
7 BOON KENG ROAD
#01-132
Singapore 330007

Document no.
Document date 25-08-2020
Customer no. 5211019114
Customer GST-ID
Dealer 30001
Job order number 2020019966/ 1
Job order date 24-08-2020
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SKF3860C	5K13G5	24-05-2012	WVWZZZ1KZCW297297	Golf 1.4 Comfo 90 TSI D7F	121

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul

Hp 90010068

6 days

25/08/2020 @ 1150

Resurvey before paint