

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 09 Sep 2020)**Parts:** N/A TOYOTA HIACE 2.5 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/SJM6666C/09/09/2020 15:10**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN (BLACK SHADE) <i>100</i>	0.00	0.00	*180.00 F ✓
2	1		*REAR BUMPER ALUMINIUM <i>DD</i>	0.00	0.00	*450.00 F ✓
Total Parts (S\$)						630.00

F=Franchise part.

Jin Auto Services Pte Ltd/SJM6666C/09/09/2020 15:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS