

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 24/08/2020

3P INSURANCE: NTUC

MODEL: HYUNDAI I 40

SURVEYOR: LKK

VEH NO.: SHA4532E

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Door (LH)	1		\$2,256.40
	Rear Door (LH)	1		\$2,201.10
	Front Door Mirror LH	1		\$670.00
	Rear Fender LH	1		\$2,171.40
	Front Door Outer Handle LH	1		\$36.30
	SPARE PARTS SUB TOTAL			\$7,335.20
	LESS 20%			\$1,467.04
	DISCOUNTED SPARE PARTS TOTAL			\$5,868.16
	FRT Door Tel No. Sticker (LH/RH)			\$75.00
	Rear Door ComfortDelGro & Apps Sticker (LH/RH)			\$80.00
	Frt LH door radio sticker			\$100
	Rear LH door sticker			\$100
	NETT TOTAL			\$155.00
	SPARE PARTS & NETT TOTAL			\$6,023.16
	Panel Beating			\$900.00
	Spray Painting			\$800.00
	Wiring Charge			\$50.00
	Tuff Kote			\$40.00
	Transfer of Door Mechanism			\$120.00
	Labour Total			\$1,910.00
	ESTIMATE TOTAL			\$7,933.16

b/✓
 Ro
 fma
 Ro
 ant
 2962.70
 2370.16

Nett ✓
 Nett ✓
 ✓
 ✓
 355

560.
 760
 30
 30
 60

4105.16
 4105.16
 3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.