

Shirley Hiew (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Friday, 4 September 2020 10:22 am
To: Shirley Hiew (LKK Auto)
Subject: Re: SMA 8353U DOA - 24/08/2020

Hi Shirley,

Audit check done for SMA8353U, found repair estimate without parts prices. Thus parts prices need verification when provided.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 3 September 2020 6:08 PM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: SMA 8353U DOA - 24/08/2020

Hi Simon,

Kindly check the new TP Cases.

Documents uploaded in view system,

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.