

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 03 Sep 2020

Preliminary Advice

Insured Vehicle No : SLW7501L
TP Vehicle No : SMA8353U
Make : HYUNDAI ELANTRA
Date of Inspection : 26/06/2020
Inspection At : Vermogen Ace Pte Ltd (jln Lam Huat) (HQ)
60 Jalan Lam Huat, #03-35/36
Singapore 737869

Accident Date : 24/08/2020
Assignment Date : 25/08/2020
Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

Parts claimed are/not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,550.00
Revised Amount	:S\$	1,110.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,110.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Some parts items are still pending parts prices.