



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300

GST Registration : 200719980C

E-mail : ccacpl@singnet.com.sg

TO: MS FIRST CAPITAL

ATTN: MOTOR CLAIMS DEPT

DATE : 26-Aug-20

JOB TYPE : 3RD PARTY CLAIM

VEH NO : SMS8870Z

MARK : TOYOTA

MODEL : RUSH 1.5X A

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: SOH SAI CHEOW

ADDRESS:

CHASSIS NO : J200E0022762

ENGINE NO:

CONTACT NO H/P:

ACCIDENT DATE : 22/08/2020

TEL:

OWNERS INSURER : CHINA TAIPING

POLICY NO: DMPCSNW00018392000

QUOTATION SUMMARY

REQUESTOR CONTACT :

CLAIM DETAIL: PARTS

HO / 67810300 / 96214666

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILDOOR <i>Body</i>	1	\$893.90	\$893.90 ✓
2	REAR TAILDOOR HINGE <i>11</i>	2	\$198.10	\$396.20 X
3	REAR TAILDOOR LOCK <i>11</i>	1	\$295.70	\$295.70 X
4	REAR TAILDOOR TRIM	1	\$286.80	\$286.80 ?
5	REAR TAILDOOR WEATHER STRIP	1	\$386.40	\$386.40 ?
6	REAR TAILDOOR SPARE TYRE COVER <i>CM</i>	1	\$1,598.00	\$1,598.00 ✓
7	REAR TAILDOOR SPARE TYRE COVER BASE <i>CM</i>	1	\$590.00	\$590.00 ✓
8	REAR TAILDOOR SPARE TYRE BRACKET	1	\$298.10	\$298.10 ?
9	REAR BUMPER <i>20/22</i>	1	\$1,258.30	\$1,258.30 ✓
10	REAR BUMPER RETAINER <i>11</i>	2	\$58.60	\$117.20 X
11	REAR BUMPER TOWING COVER <i>11</i>	1	\$28.10	\$28.10 X
12	REAR BUMPER REFLECTOR RH & LH <i>11</i>	2	\$76.70	\$153.40 X
13	REAR BUMPER CLIP <i>mm</i>	8	\$4.91	\$39.28 ✓
14	REAR TAILLAMP RH <i>11</i>	1	\$374.90	\$374.90 X
15	REAR END PANEL	1	\$317.80	\$317.80 ?
16	REAR END PANEL GARNISH	1	\$110.87	\$110.87 ?
17	REAR FLOOR PANEL <i>11</i>	1	\$1,090.90	\$1,090.90 X
18			\$-	\$-
19			\$-	\$-

PARTS PRICE : \$8,235.85

LESS 25% : \$2,058.96

SUB TOTAL PRICE : \$6,176.89

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	SEALANT <i>Rec</i>	2	\$35.00	\$70.00 <i>40</i>
2	REVERSE SENSOR <i>shuld</i>	1	\$250.00	\$250.00 <i>200</i>
3	REAR EMBLEM 'RUSH' <i>Rec</i>	1	\$30.00	\$30.00 <i>✓</i>
4	REAR NUMBER PLATE & HOLDER <i>Rec</i>	1	\$60.00	\$60.00 <i>X</i>
5	FRONT NUMBER PLATE & HOLDER <i>Rec</i>	1	\$60.00	\$60.00 <i>40</i>
6	REAR TAILDOOR BODY SEALANT <i>nn</i>	1	\$60.00	\$60.00 <i>X</i>

S/N PARTS PRICE :

\$530.00

TOTAL PARTS PRICE :

\$6,706.89

CLAIM DETAIL : LABOURS & SPRAY PAINTING

No	JOBS DESCRIPTION	PRICE	REVISED PRICE	
1	LABOUR --REAR	\$1,000.00	<i>800</i>	
2	CHECK WIRING	\$70.00	<i>20</i>	
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$80.00	<i>60</i>	
4	SPRAY PAINTING --REAR	\$900.00	<i>780</i>	
5	TO REMOVE & REFIT REAR TAILDOOR. REAR TAILDOOR LOCK INNER & OUTER, REAR TAILDOOR HANDLE, WIPER MOTOR, SWITCH, TRIM BOARD & ALL EMBLEMETC.	\$90.00	<i>60</i>	
6	TO REMOVE & REFIT REAR WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$120.00	<i>✓</i>	
7	TO REMOVE & REFIT INNER ITEM FOR NECESSARY BODY WORK. FIXING OR PANEL BEATING	\$80.00	<i>60</i>	
8	TO REMOVE/REFIT REAR CAMERA	\$80.00	<i>40</i>	
9	TO APPLY BODY SEALANT	\$60.00	<i>11X</i>	
10	REINSTALL REAR BUMPER SENSORS	\$80.00	<i>X</i>	
11	LABOUR--FRONT	\$400.00	<i>200</i>	
12	SPRAY PAINTING--FRONT	\$500.00	<i>200</i>	
TOTAL LABOUR & SPRAY PAINTING PRICES:		\$3,460.00		

VEHICLE NO : SMS8870Z

ESTIMATE REPORT

TOTAL LABOUR COST : \$3,460.00

TOTAL PARTS COST : \$6,706.89

TOTAL REPAIR COST : \$10,166.89

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

PART BY PART OR LUMP-SUM : LKK Auto Consultants hence notify the Repairer of the following:

DATE OF SURVEY : • To resurvey before/after spray painting

SURVEY BY : • To display damaged part(s) during resurvey

CONTACT NO : • Parts prices are subject to confirmation

FAX NO : • Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

LUMP-SUM AMOUNT OR COST OF SUPPLEMENTARY item(s) must be resurveyed and REPAIR WOULD BE REVISED if subject to final approval from Insurance Company

NOTE :

SUPPLEMENT REPAIR IS REQUIRED

Acknowledged by Repairer

Signature:

Date:

not Acknowledged

4/5/20

5 day

Take photo of the

26/8/20