

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 01 Sep 2020

Preliminary Advice

Vehicle No	: SFW3104Y	Accident Date	: 21/08/2020
Make	: AUDI Q7	Policy No.	: 1900261253
Assignment Date	: 27/08/2020	Excess	: S\$0.00
Date of Inspection	: 27/08/2020	Est. Duration of Repair	: 8
Inspection At	: 24 BENOI SECTOR		
	REPAIRER : PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,842.00 (Includ Supplementary \$9,315.00)
Revised Amount	:S\$	30,056.00 (Includ Supplementary)
Check Items (Estimated)	:S\$	21,319.00
Total	:S\$	51,375.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	240,000.00
COE / PARF Rebate	:S\$	94,169.00
Salvage Value	:S\$	
Margin for Repair	:S\$	145,831.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :