

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46806

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0603/2020/NS
Date : 26-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Rasul,

4 days - ok - Jy - 24 Oct 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Srivats Hariharan
Address : 89 Bukit Drive
#03-22
Singapore 587846
Telephone : HP +65 81557230
Type of Claim : Own Damage Claim
Policy No. : 190012167
Vehicle No : **SMM 8993 J**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-19
Engine No : CHZ C27822
Chassis No : WAUZZZ8V9K1025247
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Aug-20
Place of Accident : Exit 11(AYE City) Towards Clementi Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMM 8993 J

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	280.00	\$ 280.00
2	To remove and transfer lhs headlight control unit and power module.	S/N \$	350.00	\$ 250.00
3	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
4	To respray front bumper.	\$	900.00	\$ 550.00
5	Supplementary	\$	1,700.00	\$ 800.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,472.00	\$ 2,572.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 8993 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 38.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 159.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 530.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	\$ 293.00	
7	FRONT BUMPER COVER TRIM - LH	\$ 161.00	
8	RADIATOR GRILLE	\$ 1,406.00	\$ 1,124.80
9	RADIATOR GRILLE CLOSING ELEMENT	\$ 189.00	\$ 150.80
10	AIRCON STICKER	NEC \$ 8.00	\$ 5.68
11	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 186.00	
13	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 715.00	\$ 571.60
14	FRONT BUMPER FOAM FILLER PIECE	\$ 187.00	\$ 149.60
15	FOAM FILLER PIECE COVER	\$ 121.00	
16	LED HEADLIGHT - LH	\$ 5,455.00	\$ 4,364.00
17	LIFT CYLINDER - LH	\$ 141.00	
18	RADIATOR AIR GUIDE - LH	\$ 24.00	
19	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
20	SUPPLEMENTARY	\$ 28.00	\$ 21.84
21	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		: \$ 12,087.00	\$ 8,048.72
TOTAL LABOUR CHARGES		: \$ 4,472.00	\$ 2,572.00
GRAND TOTAL		: \$ 16,559.00	\$ 10,620.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0603/2020/NS 16-Sep-20 Glory Tan 1 OF 1 SMM 8993 J Audi A3 Sedan 1.0 TFSI 8V	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Bonnet edge protection	\$ 28.00	\$ 21.84	
<u>Labours</u>				
1	To repair lhs front fender.	\$ 700.00	\$ 250.00	
2	To respray lhs front fender.	\$ 1,000.00	\$ 550.00	
TOTAL		\$ 1,728.00	\$ 821.84	

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant