

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Aug 2020)
Parts: 143 **HYUNDAI I40 1.7 D CRDi (A) (Catalogue Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA5637E/25/08/2020 16:15
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,106.00 FL <i>del</i>
2	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL <i>R</i>
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL <i>X</i>
4	1		*REAR BUMPER REINFORCEMENT STAY LH	20.00	0.00	*80.30 FL <i>X</i>
5	1		*REAR BUMPER SPONGE	20.00	0.00	*119.50 FL <i>X</i>
6	1		*REAR BUMPER SIDE BRACKET LH	20.00	0.00	*35.20 FL <i>new</i>
7	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	*32.00 FL <i>ant</i>
10			*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>new</i>
1			*REVERSE SENSOR	0.00	0.00	*135.70 F <i>new</i>
1			*REAR BUMPER MAT	0.00	0.00	*50.00 F <i>new</i>
Sub Total (\$\$)						2,237.10
- List Item Discount on L Items (\$\$)						410.28
Total Parts (\$\$)						1,826.82

Franchise part. L=List/ItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA5637E/25/08/2020 16:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1195.20
 20% - 956.16
 + 135.70
 SN 50
 1141.86

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 280	300.00
2	SPRAY PAINTING	New 200	250.00
3	R/I REVERSE SENSOR	New 30	120.00
Gross Labour Cost (S\$)			670.00

ComfortDelGro Engineering Pte Ltd/SHA5637E/25/08/2020 16:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9747549
-wp' 26/8/20
• 2 days
E/S Resurvey after repair
Tanpin Mahanor

1141.86
11
510
1662.86
4/5/1350
2 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged parts during resurvey
- Parts price list and confirmation
- Third party claims on "Prejudice" basis
- No if/then clauses to be used
- Suppliers to be approved and is submitted to the Insurance Company

Acknowledged by Repairer