# **SMRT Automotive Services Pte Ltd 60 WOODLANDS INDUSTRIAL PARK E4**

### 757705

**Insurer Reference:** 

**Full Report Registration: GBD5620H** 

Repairer Reference: WL/AUG2020/008 Date calculated: 10/09/2020 11:45 AM

Printed: 10/09/2020 11:46 AM

### **Summary Information**

Claim

Location: Singapore (SG) Work Provider: India International

Insurance

Printed by:

SMRT Raymond

Currency: Date of Incident: SGD 23/08/20

Claim Reference:

Estimated Repair Time: 6 Actual Repair Days:

Hire Car Start:

Hire Car End:

#### **Vehicle Details**

Vehicle

**ISUZU** Manufacturer: Model: KB(RT) Sub Model: D-MAX Model Sheet Number: 37 63 05 Registration: GBD5620H

VIN number: Odometer: **Model Specs** 

DOUBLE CAB TWO COAT METALLIC PREPARE OFF VEHICLE


#### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

AII **Underbody** 



### Labour

	Time Base 10 WU/h	Price = 50.00 SGD/h	
Code	Description	WU Price SGD	
NO NUMBER	R + R REAR BUMPER	2.0 / 10.00	
NO NUMBER	RENEW REAR BUMPER (REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	
1008	SYSTEM WIRING CHECK. 000000	/20.00*	
1009	REINSTALL R/SENSOR. 000000	30.00*	
1010	Repair side panel 000000	20.0* 30.00* 100.00	
	Labour Cost Panel / Mechanical Labour Fixed Rate	Hrs WU 2.50 25.0 125.00 50.00	
	Total of Labour	175.00	

## **Paint**

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	Respray side panel 000000	160.00*

Labour Cost - Paint
Time Paint
Total

Hrs WU Price SGD
10 WU/h
160.00

# **Spare Parts**

Code	Description	Part Number	Part Source	prices as at 2001-01-01 Price SGD
2580 2585 1005	REAR BUMPER CPL REAR COVER BUMPER RR BUMPER LWR GARNIS	93616282PA 8981023592 000000	Original / ゆり Original / (パリ Original / (Rリ	680.00 290.00 210.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Addition(+10.00%)			0.00 1,180.00 118.00
	Total			1,298.00

### **Extras**

Code	Description	Price SGD
1000	SENSOR REVERSE 000000 /short	/ 200.00*
1004	REAR NUMBER PLATE 000000 (DD)	<b>/</b> 20.00*
	Total Extras	220.00

## **Final Calculation**

	SGD	SGD
Parts Addition(+10.00%) Total Parts	1,180.00 118.00	1,298.00
Labour Time Base 10 WU/h Total 25.0 WU X 50.00 SGD/h Fixed Rate Total of Labour	125.00 50.00	175.00
Total Of Extras		220.00
Paint Work Time Base 10 WU/h Total Paint Fixed Labour Total Paint Including Material	160.00	160.00
Repair Cost Excludes GST		1,853.00
GST (+7.0%) Repair Cost Included GST		129.71 1,982.71
Comments * - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS  Assessment Note	1,853.00 - 20% 1,482.40 2/S \$ 1,50	- - 00
No assessment notes entered.	Repair day	3 days
		•