



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SDN 6616 M
HONDA CIVIC

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	BONNET X NN	1	\$1,176.00.
	2	BONNET LOCK X NN	1	\$416.00
	3	BONNET LOCK CATCH X NN	1	\$77.00
	4	BONNET INSULATOR X NN	1	\$439.00
	5	BONNET HINGE (L+R) X NN	2	\$426.00.
	6	BONNET STOPPER (L+R) X NN	2	\$174.00.
	7	BONNET RUBBER STRIP X NN	2	\$450.00.
	8	FRONT GRILLE ? / BR 224 ✓	1	\$671.00
	9	FRONT GRILLE CHROME X NN	1	\$659.00.
	10	FRONT LOGO (HONDA) ? / MR	1	\$79.00. ✓
	11	HEADLAMP (L+R) (RH) ? / BR 989 ✓ \$1,423 /	2	\$2,846.00
	12	HEADLAMP BRACKET (L+R) X NN	2	\$724.00.
	13	FRONT BUMPER / DEF 638 ✓	1	\$1,671.00
	14	FRONT BUMPER RETAINER (L+R) / BR 165 ✓	2	\$426.00
	15	FRONT BUMPER REINFORCEMENT BAR ? X NN	1	\$779.00
	16	FRONT BUMPER BRACKET (L+R) X NN	2	\$428.00
	17	FRONT BUMPER BEAM X NN	1	NIL
	18	FRONT BUMPER SPONGE X NN	1	NIL.
	19	FRONT BUMPER GRILLE X NN	1	\$379.00
	20	FRONT BUMPER FOG LAMP GARNISH (L+R) X NN	2	\$428.00
	21	FRONT BUMPER UNDERCOVER X NN	1	\$716.00
	22	FRONT FENDER (L+R) X NN	1	\$2,116.00
	23	FRONT FENDER COWLING (RH) X NN	1	\$276.00
	24	FRONT FENDER MUDFLAP (RH) X NN	1	\$204.00
	25	FRONT SUPPORT PANEL X Repair	1	\$1,079.00
	26	FRONT SUPPORT PANEL TOP GARNISH X NN	1	\$419.00
	27	AIRCON CONDENSOR X NN	1	\$1,459.00
	28	HIGH PRESSURE HOSE X NN	1	\$321.00
	29	LOW PRESSURE HOSE X NN	1	\$364.00
	30	RADIATOR X NN	1	\$2176.00
	31	SUCTION PIPE X NN	1	\$372.00
	32	DISCHARGE PIPE X NN	1	\$326.00
	33	RADIATOR FAN COWLING X NN P = \$4,270. - 20% = \$3,416	1	\$856.00
	34	RADIATOR FAN BLADE X NN	1	\$736.00
	35	RADIATOR FAN MOTOR X NN	1	\$439.00
	36	WIPER WASHER TANK X NN	1	\$407.00
	37	WIPER WASHER MOTOR X NN	1	\$489.00
		2095		
		-20%		
		1676	SUBTOTAL	\$ -
			LESS 10%	\$ -

PARTS TOTAL			\$	-
SPECIAL NETT			QTY	PRICE
1	BONNET INSULATOR CLIPS X NN		10	\$ 100.00
2	FRONT BUMPER CLIPS / MC		10	\$ 100.00
3	FRONT BUMPER LOWER X NN		1	\$ 6,000.00
4	FRONT FENDER COWLING CLIPS X NN	DN=830 ✓	10	\$ 100.00
5	FRONT FENDER MUFLAP CLIPS X NN		5	\$ 50.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS X NN		10	\$ 100.00
7	RADIATOR COOLANT X NN		1	\$ 80.00
SPECIAL NETT TOTAL				\$ 6,530.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	250	1	\$ 3,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400 500	1	\$ 2,700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$ 600.00
4	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS		1	\$ 400.00
5	TO RNR A/C CONDENSOR ASSY AND REFILL GAS		1	\$ 350.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		1	\$ 200.00
7	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.		1	\$ 800.00
8	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD		1	\$ 300.00
9	TO DO WATER LEAK TEST.		1	\$ 120.00
L= \$ 840				840 ✓
T= \$ 4280				
-20% = \$ 3424				
TOTAL				\$ 8,470.00
GRAND TOTAL COST				\$ 15,000.00

Steve (CLKK) WR AL

28/8/22, 12:30pm

3 dy

L/S

Ry AL sy

P - 1676

N - 30

L - 840

2546

L/S - 2036.80

= 2050