

(08/11/13) wef

ASS. REC. BY: *Marius*

REF:

cc6/EQ/120009115/ugz3

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SGW 41927

at Workshop m/s

R1

of

Insured:

SMC 9936X

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

£38

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7591

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

2075500 1014 4830

3/9/20 LTA #33170 cae 16-7-2027
L/S #3700 confirmed with Alan.

Veh No: *SGW 41927* Yr Regn: *7107*

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or *(M)*

Make:

Toyota V20

c.c *1497*

Colour:

Beige

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

186795

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No:

MR053HY9305008320

Gen. Cond: ☐ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/8/20

D.O.I.

28/8/20

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear 1/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS. ___ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

446 44110

not Authorized
Hulu

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE No.SGW 4192Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

28/8/20
1/543700
4 days.

1PC	BOOTLID	566.10	pp/buc	\$766.50	✓
1PC	BOOTLID OUTER HANDLE		11	\$198.10	X
1PC	BOOTLID REAR LOGO		rec	\$60.80	✓
1PC	BOOTLID INNER LOCK	185.40	stated	\$199.40	✓
1PC	BOOTLID LOCK STRIKER		11	\$89.90	X
1PC	BOOTLID WEATHERSTRIP	198.70	11	\$266.50	✓
1PC	REAR BUMPER	427.90	pp	\$655.10	✓
2PCS	REAR BUMPER SIDE RETAINERS	@\$76.50	11	\$153.00	X
2PCS	REAR BUMPER BRACKETS	@\$99.10	11	\$198.20	X
2PCS	REAR BUMPER REFLECTORS	@\$195.00 157.00	M/Scre	\$390.00	1pc
1SET	REAR BUMPER CLIPS		rec	\$50.00	✓
1PC	REAR EXHAUST		11	\$588.10	X
2PCS	REAR EXHAUST MOUNTINGS	@\$65.00	11	\$130.00	X
1PC	REAR END PANEL	601.10	pp/buc	\$655.20	✓
1PC	REAR END PANEL GARNISH	165.80	11	\$315.10	✓
2PCS	TAILLAMPS	@\$520.10 322.50	M/Scre	\$1,040.20	1pc
2PCS	TAILLAMPS HOUSING PANELS	@\$199.50	11	\$399.00	X
1PC	REAR FLOOR PANEL		11	\$911.20	X
1PC	REAR FLOOR PANEL TOP BOARD	299.20	11	\$422.50	✓
2PCS	REAR FLOOR PANEL SIDE TOOLS SPONGES	@\$389.10 302.20	M/Scre	\$778.20	1pc
2PCS	REAR FENDERS	@\$845.10	11	\$1,690.20	X
2PCS	REAR FENDER INNER SPLASH SHIELDS	@\$105.00 102.10 (252)	M/Scre	\$210.00	1pc
				\$10,167.20	

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	should	\$280.00	200
1PC	REAR END PANEL SEALANT	rec	\$50.00	✓
1PC	REAR FLOOR PANEL INSULATOR	11	\$200.00	X

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REPALENG REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$80.00	60
TO SPRAY RUST PROOFING	\$120.00	60
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO DISMANTIE & REFIX CUSHION UPHOLSTERY	\$180.00	80
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	650
TO PUTTY & SPRAY PAINTING	\$1,680.00	900
TOTAL	\$14,817.20	

3432.80
252
257460