

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOM	SOMPO INSURANCE SINGAPORE PL			CS3/SMO20009176	/QKsf3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623			Date:	16-09-2020		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	GBG 7242L	Veh. Ir	nspected	JTY 823	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2002503/MYE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign	n Date	31/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA Y15	c.c		150	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	PMYUG0520LC106H7	Colour		GREY	
	Odometer	9083 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90/80-17	DURO		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	90/80-17	DURO		5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FROM			PORTION.		
5. General Information						
	Accident Date	25/08/2020	Inspec	t Date / Time	01/09/2020 (02:57 PM)	
	Survey held at SENG HWEE MOTOR BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760					
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMO20009176/QKsf3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.