



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND
TOWER
SINGAPORE 048623

INV No. AC2006421
INV Date 16/09/2020
Reference CS3/SMO20009176/QKsf3e
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. JTY 823
Insured Veh. GBG 7242L
Claim No. CMTD2002503/MYE
Policy No.
Accident Date 25/08/2020
Inspection Date 01/09/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 02.09.2020)	60.00
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM