

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Friday, 18 September 2020 11:02 AM
To: Shiau Chan (LKKAuto)
Subject: Re: MSIG TP SJF 936A SURVEYED BY ADRIAN

Dear Shiau Chan,

Audit check done for SJF936A, found labour for removing fuel tank is not necessary. I already informed Adrian to remove.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, 18 September 2020 10:06 AM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: MSIG TP SJF 936A SURVEYED BY ADRIAN

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)