

12/12/2020

REF: CS4/ASM20009244/Ntf3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): Winnie Ho

of

ASM

Date/Time: 01/09/2020

Estimated Cost:

Bill to:

☒ OD ~~TP~~ / ~~WS~~ / ~~TP~~ RES / ~~OD~~ RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 5931Y

Insured:

at Workshop m/s T & B Motor Repairs

Tel: 6454 8007

of 160 Sin Ming Drive #08-03

Policy No:

Claim No: SOM02SZ3

Sum Insured:

Excess:

D.O.A. 28/08/2020

Make of Veh:

(Client's Record)

CA ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 01/09

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction () Estimate
	FIRE pls conduct investigation and apply SCDF report.
	Hi Naz, pls check if any modification / malfunction to vehicle that cause fire. Tks