

AUBURN AUTO PTE LTD
 UEN : 200805305G
 176 Sin Ming Drive Autocare #04-18, Singapore 575721
 Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Steve (LKK)
 01/09/20
 without prejudice
 L/S
 resurvey after spray
 6 repair days

Vehicle Number : SJY9352A (DOA : 25 Aug 2020)

Make & Model :
 Volkswagon Jetta

Quantity	Description	Repairer's Estimate	
SIDE			
1	Bumper Strip X NN	\$200	
1	Right Side Fender X NN	\$250	
1	Right Wing Mirror X NN	\$350	
1	Under Tray Cover X NN	\$350	
1	Right Headlight X NN	\$400	
1	Condenser X NN	\$450	
1	Radiator X NN	\$450	
1	Reinforcement Bar Sponge X NN	\$450	
1	Front Right Door Replace (Rear RH door) ✓	DD \$2,000	1255 ✓
1	Front Right Door Lock (Rear RH door lock) ✓	Jammed \$200	292 ✓
BACK			
1	Reverse Sensor X NN	\$200	
1	Right Tail light bracket X NN	\$250	
1	End Panel Garnish X NN	\$500	
1	Tail lamp lower bracket X NN	\$120	
1	Rear right bumper retainer X BR NN	\$500	
1	Rear right tail light bracket X NN	\$150	
1	Rear right door body lining (Weatherstrip) ✓	NEC \$450	188 ✓
1	Rear right rim & tyre (Rim only) ✓	CUT \$800	400 ✓
1	Rear right wheel bearing X NN	\$800	
1	Bootlid Weatherstrip X NN	\$120	
2	Rear right & left mudguard X Repair	\$200	
1	Bumper Bracket X Repair	\$1,200	
2	Rear light & left absorber X NN	\$2,400	
1	Rear Bumper ✓ BR	\$2,000	1267 ✓
LABOUR & MISC			
1	Checking of wiring, lighting and resetting	\$850 30 ✓	
1	Remove and refit rear undercarriage	\$500 50 ✓	
1	Wheel alignment	\$300 60 ✓	
1	Remove and replace damaged parts	\$1,000 X	
1	Apply undercoating on repaired and replaced panel	\$800 30 ✓	
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 600 ✓	
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 600 ✓	
Total Repair Cost :		\$20,440	1370

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To replace damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a 'Without Prejudice' basis
 • No legal modification(s) is allowed
 • Supplementary items must be resurveyed and is subject to final approval from insurance Company
 Authorised by Repairer
 Signature: _____
 Date: _____

P - 3061.80 L/S - 3545.44
 L - 1370 = 3500
 4431.80

3402
 -10%
 3061.80