



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20009253/Uqf3e2

73 BRAS BASAH ROAD

Date: 14-09-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 186U	Veh. Inspected	SMM 4832S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1101525-002	Excess (\$)	0.00
Assign From	HAZALYSA BTE IBRAHIM	Assign Date	01/09/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA CX-3 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6DK2W7AK0417448	Colour	BLUE
Odometer	21956 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/08/2020	Inspect Date / Time	01/09/2020 (09:54 AM)
Survey held at	TONY AUTOMOTIVE PTE. LTD 8 KAKI BUKIT AVENUE 4 #04-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------