## COMFORT DELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

Vehicle No.: SHC3851E Make : TOYOTA Model : PRIUS DOA : 31.08.2020

Date : 31.08.2020 Insurance: NTUC MVA : CHIANG

Admin

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
	REAR TRUNK LID LOGO (PRIUS)			\$60.80
	REAR TRUNK LID LOGO (HYBRID)			\$52.40
	REAR TRUNK LID LOGO (TOYOTA STAR)		1 1	\$52.90
	REAR BUMPER		\$112.70	\$458.60
	REAR BUMPER UNDER COVER			\$552.60
	REAR BUMPER SIDE RETAINER LH/RH			\$225.40
	REAR BUMPER UNDER COVER CENTRE			\$232.00
	REAR BUMPER TOWING COVER		\$82.70	
	REAR BUMPER CLIPS			\$22.00
	REAR BUMPER REINFORCEMENT			\$318.80
	SUB TOTAL		Santa la	\$2,947.90
	LESS 25%		Carlotte St	\$736.98
	DISCOUNTED TOTAL			\$2,210.93
	REAR TRUNK LID APPS STICKER			\$40.00
	REAR TRUNK LID COMFORT & TEL NO. STICKER		1	\$60.00
	REAR BUMPER REVERSE SENSOR	1		\$135.70
			Less 1020	\$235.70
	Labour Charge			
	Panel Beating			\$640.00
	Spray Painting Charge			\$500.00
	Wiring Charge			\$90.00
	Tuff Kote			\$120.00
	Remove/Refix Reverse Sensor			\$90.00
	TOTAL LABOUR		A Section of the	\$1,440.00
	ESTIMATE TOTAL		3,936.63	\$3,886.63

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfin 9749)749 was then
We 31/8/20 & 4pm
Ple Resmy before pent. 3olys
furfur @ Whento.om

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: