



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

TAX INVOICE

14 April 2021

WO202009-0008
HHTPCCLAIMS20-103

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SMH2585U & SH6744E ON 28/08/2020 ALONG PIE NEAR POLICE ACADEMY TOWARDS CHANGI AT ABOUT 1730 HOURS

Insured : ISMAIL BIN AGIL
Vehicle Registration No. : SMH2585U
Vehicle Make : TOYOTA
Vehicle Model : VIOS 1.5 G (AUTO)
Vehicle Chassis No. : MR2B23F3001160629
Policy No. : 5115145219
Date of Accident : 28/08/2020

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Bonnet		\$ 295.00
2	1	Bootlid		\$ 300.00
3	1	Bootlid Lock		\$ 155.00
4	1	Boot Seal		\$ 85.00
5	1	Clip Fastening		\$ 15.00
6	1	Clip Fastening		\$ 15.00
7	1	Front Bumper		\$ 220.00
8	1	Front Bumper Grille		\$ 165.00
9	1	Front Grille Top		\$ 18.00
10	1	Front Manufact Badge		\$ 35.00
11	1	Frt Grille Center		\$ 45.00
12	1	Grille Garnish Cover		\$ 55.00
13	1	Grille		\$ 75.00
14	1	L/Daytime Headlamp		\$ 178.00
15	1	L/F Air Duct		\$ 45.00
16	1	L/F Bumper Bracket		\$ 40.00
17	1	L/Lwr Vent Air Chann		\$ 48.00
18	1	L/R Bumper Bracket		\$ 65.00
19	1	L/R Lamp Bracket		\$ 35.00
20	1	L/R Reflector		\$ 120.00
21	1	Left Headlamp Assy		\$ 320.00
22	1	Lock Carrier Strut		\$ 65.00
23	1	R/F Bumper Bracket		\$ 40.00
24	1	R/R Bumper Bracket		\$ 65.00

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

TAX INVOICE

14 April 2021

WO202009-0008
HHTPCLAIMS20-103

ACCIDENT INVOLVING SMH2585U & SH6744E ON 28/08/2020 ALONG PIE NEAR POLICE ACADEMY TOWARDS CHANGI AT ABOUT 1730 HOURS

Tax Invoice for vehicle SMH2585U - TOYOTA VIOS 1.5 G (AUTO)

S/N	Quantity	Description	Unit Price S\$	Amount S\$
25	1	Rad Top Garnish		\$ 15.00
26	1	Rear Boot Lamp		\$ 155.00
27	1	Rear Bumper		\$ 200.00
28	1	Rear Bumper Reinf		\$ 125.00
29	1	Rear Fender Inner		\$ 45.00
30	1	Rear Fender Shield		\$ 10.00
31	1	Rear Manufact Badge		\$ 35.00
32	1	Rear Panel		\$ 295.00
33	1	Reverse Sensor		\$ 220.00
34	1	Right Headlamp Assy		\$ 320.00
35	1	RR Manufacture Badge		\$ 25.00
				\$ 3,944.00
				Cost + 10% \$ 394.40
				4,338.40
36	1	Sundry		\$ 85.07
				\$ 85.07
				Cost + 2.% \$ 1.70
				86.77
37	1	Front Number Plate	NETT	\$ 35.00
Total Labour				\$ 930.00
Total Paint/Material				\$ 1,457.83
				\$ 6,848.00
				7% GST \$ 479.36
Total				\$ 7,327.36



Authorised by Claims Dept